AUTOTRONICA Y ELECTRONICA PORTUGAL

Fig. 9: Wiring Diagram (5.0L & 5.8L - Bronco & Pickup)
1992 Ford Pickup F150



 © 2004 Mitchell Repair Information Company, LLC.