


**AUTOTRONICA Y ELECTRONICA PORTUGAL**  
INDEPENDENCIA 507  
EL FUERTE, SINALOA 81820

**Fig. 11: Identifying PCM/TCM Input & Output Device  
Locations: Identifying Component Locations**  
Courtesy of AMERICAN HONDA MOTOR CO., INC.  
1996 Honda Accord DX



96H30996